



Handler[®] 125 EZ

COMPARISON CHART

Handler 125 EZ Advantages	NEW! Hobart Handler 125 EZ	Hobart Handler 125	Lincoln Weld-Pak HD, Handy Core	Lincoln Weld-Pak 100HD, Pro-Core 100	Campbell Hausfeld Farmhand WF2054	Clarke 130 EN MIG (No gas or gas)
Easiest, Quickest to Set with Single Knob Control Just Select Thickness. No Parameter Chart Req'd	One single knob controls both voltage and wire feed speed based on mild steel thickness selected	4 Voltage Settings Separate Wire Feed Speed Welding Guide on Door	High, Low, 1, 2 Separate WFS Control Welding Guide on Door	4 Voltage settings Separate WFS Control Welding Guide on Door	Only 2 Voltage Settings Separate WFS Control Welding Guide (No WFS)	4 Voltage Settings Separate WFS Control No Welding Guide on Door
Highest Output for a Gasless Model to weld 3/16" mild steel with Flux-cored Wire	90A @ 19V, 20% Max 125 Amps Max 3/16" Not upgradeable for MIG	90A @ 19V, 20% Max 125 Amps Max 3/16" 22 ga-1/8" MIG with Opt. Kit	70A @ 17V, 20% Max 88 Amps Max 1/8" Not Upgradeable for MIG	88A @ 18V, 20% Max 100 Amps Claims up to 1/4" multi-pass MIG with Opt. Kit	70A @ 18V, 20% Max 85 Amps Claims Max 3/16" Not Upgradeable for MIG	60A @21V, 40% Max 3/16" Needs Gas & Regulator for MIG
Spare tips holder located above feedhead	H-9 Torch, 8 ft. Hard wired Spare Tip Holder	H-9 Torch, 8 ft. Hard wired Spare Tip Holder	Hard wired torch, 8 ft N/A	Magnum 100L, 10 ft. N/A	8 ft. Hard wired torch N/A	Hard wired torch, 7 ft N/A
Heavier Cable for less Power Loss	10 ft. 6 AWG Work Cable Work Clamp w/insl Covers	10 ft. 6 AWG Work Cable Work Clamp w/insl Covers	7 ft. 8 AWG Work Cable Bare Work clamp	10 ft. 8 AWG Work Cable Bare Work clamp	5'4" Work Cable 9 AWG Work Clamp w/insl Covers	6 ft Work Cable Bare Work Clamp
Sample Spool of .030" Flux-cored Wire for welding of thinner material	4" spool, .030 Flux-cored Opt. Hub for 8" spools	4" spool, .030 Flux-cored Opt. Hub for 8" spools	.035 Flux-cored Wire Holds 8" or 4" Spools	.035 Flux-cored Wire Opt. Hub for 8" spools	4" spool .035 Flux-cored Holds 8" or 4" Spools	4" spool, Flux-cored 8" spool difficult to install
Easy changeover for new spool of wire or wire diameter change Not Applicable, N/A	Durable Plastic Feedhead Quick Release Tension Arm Quick-Change Dual Groove N/A	Durable Plastic Feedhead Quick Release Tension Arm Quick-Change Dual Groove Easy Polarity Changeover	Plastic Feedhead Quick Release Tension Arm Quick-Change Dual Groove N/A	Plastic Feedhead, Small Roll Quick Release Tension Arm Dual Groove, Set Screw Easy Polarity Changeover	Plastic Feedhead Quick Release Tension Arm Dual Groove, Two Screws N/A	Plastic Feedhead Quick Release Tension Arm Dual Groove, Set Screw Easy Polarity Changeover
Hobart Quality Product with Proven Hobart Warranty and Service. 1-800-332-3281 Technical Help Line www.HobartWelders.com Informative Website and "Weld Talk" Forum. Parts readily available	Input Power: 115V, 20A 6 ft. Power Cord w/plug Rugged Accessories Sold Separately Self-resetting Thermal Overload Short Circuit Protection 50 lbs. Hobart 5/3/1 Warranty Manufactured in USA	115V, 20A 6 ft. Power Cord w/plug Rugged Accessories Sold Separately Self-resetting Thermal Overload Short Circuit Protection 50 lbs. Hobart 5/3/1 Warranty Manufactured in USA	115V, 20A 6 ft. Power Cord w/plug Cheap Handshield Self-resetting Thrmal Overload Short Circuit Protection 46 lbs. 3 Yr / 90 days Imported from Poland	115 V input 6 ft. Power Cord w/plug Cheap Handshield #10 Self-resetting Thermal Overload Short Circuit Protection 47 lbs. 3 Yr Warranty / 90 days Manufactured in USA	115 V input 5.5 ft. Cord w/plug Cheap Handshield Plastic Hammer/brush Self-resetting Thermal Overload Short Circuit Protection 36 lbs. Limited 5 yr Imported from China	115 V input 6.5 ft. Power Cord, Front Exit But only 4.5 ft. From Rear of Unit 54 lbs. 10/2 Year Limited Manufactured in Italy

Competitive information taken from product publications, subject to change.